



Westpac Materials

Quick Identifier: Common Name (used on label and list)	Product Code:	Packaging:	Quick Identifier: Common Name (used on label and list)	Product Code:	Packaging:
Red Dot All-Purpose	18040	47.0 lb box	Blue Dot Extreme	18210	46 pound box
Blue Dot Taping	18200	46.0 lb box	All-Purpose	18680	12 lb bucket
Green Dot Topping (tinted)	18230	49.0 lb box	All-Purpose	18720	62 lb bucket
Green Dot Topping (white)	18220	49.0 lb box	Taping Blue Dot	18740	62 lb bucket
Black Dot Topping	18360	49.0 lb box	Topping (white)	18760	62 lb bucket
Red Dot Mid-Weight All-Purpose	18380	3.59 gal box	Topping (tinted)	18780	62 lb bucket
Taping & Topping	18180	46.0 lb box	Mid-Weight All-Purpose	18800	4.76 gal bucket
White Dot All-Purpose	18100	46.0 lb box	Light Weight All -Purpose	55410	1 quart bucket
Blue Dot Light Weight Taping	18205	3.59 gal box	Light Weight All -Purpose	55420	1 gallon bucket
Light Weight All -Purpose	18045	3.59 gal box	Taping & Topping	18725	62 lb bucket
Green Dot Light Weight Topping	18250	3.59 gal box	All-Purpose (Export)	18681	12 lb bucket
Light Weight Taping & Topping	18170	3.59 gal box	All-Purpose (Export)	18721	62 lb bucket
Taping & Topping Extreme	18190	46.0 lb box			

Section 1 – Product Name & Synonyms:		“Joint Compound”	
Manufacturer’s Name	WestPac Materials, LLC.	Emergency Telephone:	714-974-6837
Street	341 W. Meats Ave.	Other Information:	
City, State, and ZIP	Orange, CA 92865	FAX:	714-637-9033
Date Prepared:	December 21, 2006	Web-Site	WestPacmaterials.com

Section 2 – Hazardous Ingredients / Identity				
<i>THE ABOVE PRODUCTS MAY CONTAIN THE FOLLOWING COMPONENTS:</i>				
Hazardous Component(s) Chemical & Common name:	OSHA PEL (TWA)	ACGIH TLV (TWA)	% - Optional	CAS Number
Calcium Carbonate (limestone)	15 mg/m ³ ** 5 mg/m ³ *	10 mg/m ³ (e) NIC-WD		1317-65-3
Mica	20 mppcf ₂	3 mg/m ³ R		12001-26-2

341 West Meats Avenue, Orange, California 92865
 Phone: (714) 974-6837 Toll Free: (866) 974-6837 FAX: (714) 637-9033

Section 2 – Hazardous Ingredients / Identity				
THE ABOVE PRODUCTS MAY CONTAIN THE FOLLOWING COMPONENTS:				
Perlite	15 mg/m ³ ** 5 mg/m ³ *	TLV withdrawn		93763-70-3
Starch	15 mg/m ³ ** 5 mg/m ³ *	10 mg/m ³ (e)		9005-25-8
Silica - Crystalline, Quartz ₁	<u>30 mg/m³*</u> % SiO ₂ + 2 <u>10 mg/m³**</u> % SiO ₂ + 2	0.025 mg/m ³ _R	~ .01 – 1.5 %	14808-60-7
Talc (containing no asbestos fibers)	20 mppcf ₂	2 mg/m ³ (e), _R		14807-96-6
Vinyl acetate		10 ppm 15 ppm***		108-05-4
Ethyl acrylate	25 ppm***	5 ppm TWA 8 hour 15 ppm***	< 1 ppm	140-88-5
Acetaldehyde	200 ppm 360 ppm***	25 mg/m ³ _R 45 mg/m ³ _R ***	< 0.5 ppm	75-07-0
<p>* Respirable fraction (PEL) ** Total dust (PEL) or Inhalable Particulate (TLV) *** STEL/CEIL – STEL stands for Short-Term Exposure Limit. Usually a 15 – minute time-weighted average (TWA) exposure that should not be exceeded at any time during a workday, even if the 8-hour TWA has not been exceeded. CEIL stands for Ceiling (C) - the concentration that shall not be exceeded during any part of the working exposure. NIC – TLV Notice of Intended Changes NIC – WD: Notice of Intended Change; Withdraw TLV SEN – TLV-confirmed potential for worker sensitization as a result of dermal contact and/or inhalation exposure, based on the weight of scientific evidence. IV – Measured as inhalable fraction and vapor</p> <p>₁ - Present as a natural occurring contaminant, ACGIH Threshold limit values lists Silica-Crystalline Quartz as “A2- Suspected Human Carcinogen” ₂ - <1% crystalline silica (Quartz). (e) - The value is for particulate matter containing no asbestos and <1% crystalline silica. R – Measured as respirable fraction of the aerosol.</p>				

OTHER INGREDIENTS / IDENTITY – This information is provided for those individuals who may be sensitive to amines			
Hazardous Component(s) Chemical & Common name:	OSHA PEL	% - Optional	CAS Number
2 – Hydroxy Amino Ethanol	Not established	0.14 – 0.23 %	34375-28-5
1,3,5-Tris(β-hydroxyethyl)-hexahydro-1,3,5-triazine	Not established	0.14 – 0.23 %	4719-04-4
VOC's (Diethylene Glycol)		0.4 – 1.2 %	111-46-6

341 West Meats Avenue, Orange, California 92865
 Phone: (714) 974-6837 Toll Free: (866) 974-6837 FAX: (714) 637-9033

SECTION 3 – PHYSICAL & CHEMICAL CHARACTERISTICS			
Boiling Point	N/A	Solubility in Water	Less than 3%
Specific Gravity (H ₂ O = 1)	0.9 – 2.3	Reactivity in Water	N/A
Vapor Pressure (mm Hg)	N/A	pH	7 – 9
Vapor Density (Air = 1)	N/A	Melting Point	N/A
Appearance and Odor		Buff color paste with low odor	
VOC (total g/l, less water)		< 27 g/l	

SECTION 4 – FIRE & EXPLOSION DATA			
Flash Point	N/A	Non-Combustible (?)	Yes
Auto-Ignition Temperature	N/A	Flammability Limits in Air (% volume)	N/A
Special Fire Fighting Procedures	None	LEL Lower	N/A
Unusual Fire and Explosion Hazards	None	UEL Upper	N/A

SECTION 5 – PHYSICAL HAZARDS (REACTIVITY DATA)			
Stability	Unstable []		Stable [X]
Conditions to Avoid	None		
Incompatibility (Materials to Avoid)	Acids		
Hazardous Decomposition Products	May release CO ₂ when heated to decomposition		
Hazardous Polymerization	Will Not Occur [X]		May Occur []

SECTION 6 – HEALTH HAZARDS							
Acute	Inhalation of dust may cause irritation of upper respiratory system			Chronic	Long term exposure to high dust levels may impair lung function		
Signs and symptoms of Exposure				N/A			
Medical Condition Generally Aggravated by Exposure				Respiratory problems			
Chemical Listed as Carcinogen or Potential Carcinogen Y – Yes N – No or Not established P – Potential	Crystalline Silica	ACGIH TLV P - [A2]	NIOSH Yes [Ca]	NTP Yes [K]	IRAC Monograph Yes – [1]	OSHA N []	
	Vinyl Acetate	ACGIH TLV N - [A3]	NIOSH No	NTP N []	IRAC Monograph P- [2B]	OSHA N []	
Emergency and First Aid Procedures		Persons exposed to large amounts of airborne dust should leave the area to avoid the nuisance particulate material					
Routes of Entry		Inhalation	Remove to fresh air				
		Eyes	Wash with water for 15 minutes – call physician				
		Skin	Wash with soap and water				
		Ingestion	Call physician				

341 West Meats Avenue, Orange, California 92865
 Phone: (714) 974-6837 Toll Free: (866) 974-6837 FAX: (714) 637-9033

SECTION 7 – SPECIAL PRECAUTIONS AND SPILL / LEAK PROCEDURES	
Precautions to be taken in Handling and Storage	None
Other Precautions	None
Steps to be Taken in Case Material is Released or Spilled	Contain and Scoop materials into waste container for disposal
Waste Disposal Methods	Dispose of in accordance with all federal, state, and local regulations

SECTION 8- SPECIAL PROTECTION INFORMATION/CONTROL MEASURES			
Respiratory Protection (specify type)	NIOSH / OSHA approved respirator for dust when using this product. There is limited evidence that crystalline silica (quartz) causes cancer in humans.		
Ventilation	Local exhaust preferred; Mechanical Exhaust satisfactory	Special N/A	Other N/A
Protective Gloves	Yes		
Eye Protection	Safety glasses or goggles		
Other Protective Clothing or Equipment	None		
Work / Hygienic Practices	Avoid dry sanding. Wet sanding or sponging is preferred.		

NFPA Ratings
 Health: 0
 Fire: 0
 Reactivity: 0



HIMS Rating
 Health: 0*
 Fire: 0
 Reactivity: 0



0 = Minimal Hazard 1 = Slight Hazard 2 = Moderate Hazard 3 = Serious Hazard 4 = Severe Hazard

The information and data herein are believed to be accurate and have been compiled from sources believed to be reliable. It is offered for your consideration, investigation and verification. Buyer assumes all risk of use, storage and handling of the product in compliance with applicable federal, state and local laws and regulations. WestPac Materials, LLC., MAKES NO WARRANTY OF ANY KIND, EXPRESSED OR IMPLIED, CONCERNING THE ACCURACY OR COMPLETENESS OF THE INFORMATION AND DATA HERIN. WestPac Materials, LLC., will not be liable for claims relating to any party's use of or reliance on information and data contained herein regardless of whether it is claimed that the information and data are inaccurate, incomplete or otherwise misleading.

341 West Meats Avenue, Orange, California 92865
 Phone: (714) 974-6837 Toll Free: (866) 974-6837 FAX: (714) 637-9033