



# Westpac Materials

<b>Quick Identifier:</b> Common Name (used on label and list)	Product Code:	Packaging:	<b>Quick Identifier:</b> Common Name (used on label and list)	Product Code:	Packaging:
Fast Set 20	22105	25 lb bag	Fast Set Lite 180	22168	18 lb bag
Fast Set 40	22107	25 lb bag	Fast Set Lite 180	22197	39 lb bag
Fast Set 90	22115	25 lb bag	Fast Set High Density 20	22200	25 lb bag
Fast Set Lite 5	22164	18 lb bag	Fast Set High Density 40	22203	25 lb bag
Fast Set Lite 5	55310	4.5 lb box	Fast Set High Density 90	22205	25 lb bag
Fast Set Lite 20	22165	18 lb bag	Super Set MH 20	22124	18 lb bag
Fast Set Lite 20	55330	4.5 lb box	Super Set MH 40	22125	18 lb bag
Fast Set Lite 40	22166	18 lb bag	Super Set MH 60	22126	18 lb bag
Fast Set Lite 90	22167	18 lb bag	Super Set MH 90	22127	18 lb bag

<b>Section 1 – Product Name &amp; Synonyms:</b>		Fast Set, Fast Set Lite, Super Set, & Fast Set High Density	
<b>Manufacturer's Name</b>	WestPac Materials, LLC.	<b>Emergency Telephone:</b>	714-974-6837
<b>Street</b>	341 W. Meats Ave.	<b>Other Information:</b>	
<b>City, State, and ZIP</b>	Orange, CA 92865	<b>FAX:</b>	714-637-9033
<b>Date Prepared:</b>	December 21, 2006	<b>Web-Site</b>	WestPacmaterials.com

<b>Section 2 – Hazardous Ingredients / Identity</b>				
<i>THE ABOVE PRODUCTS MAY CONTAIN THE FOLLOWING COMPONENTS</i>				
Hazardous Component(s) Chemical & Common name:	OSHA PEL	ACGIH TLV	% - Optional	CAS Number
Calcium Carbonate (limestone)	15 mg/m <sup>3</sup> ** 5 mg/m <sup>3</sup> *	10 mg/m <sup>3</sup> (e) NIC-WD		1317-65-3
Calcium Sulfate (Plaster of Paris)	15 mg/m <sup>3</sup> ** 5 mg/m <sup>3</sup> *	10 mg/m <sup>3</sup> I		7778-18-9
Mica	20 mppcf <sub>2</sub>	3 mg/m <sup>3</sup> R		12001-26-2
Hazardous Component(s) Chemical & Common name:	OSHA PEL	ACGIH TLV	% - Optional	CAS Number
Perlite	15 mg/m <sup>3</sup> ** 5 mg/m <sup>3</sup> *	TLV withdrawn		93763-70-3
Starch	15 mg/m <sup>3</sup> ** 5 mg/m <sup>3</sup> *	10 mg/m <sup>3</sup> (e)		9005-25-8
Talc (containing no asbestos fibers)	20 mppcf <sub>2</sub>	2 mg/m <sup>3</sup> (e), R		14807-96-6
Silica, Quartz 1	<u>30 mg/m<sup>3</sup>*</u> % SiO <sub>2</sub> + 2  <u>10 mg/m<sup>3</sup>**</u> % SiO <sub>2</sub> + 2	0.025 mg/m <sup>3</sup> R	< 20 %	14808-60-7

341 West Meats Avenue, Orange, California 92865  
 Phone: (714) 974-6837 Toll Free: (866) 974-6837 FAX: (714) 637-9033

**Section 2 – Hazardous Ingredients / Identity**

**THE ABOVE PRODUCTS MAY CONTAIN THE FOLLOWING COMPONENTS**

\* Respirable fraction (PEL)  
 \*\* Total dust (PEL) or Inhalable Particulate (TLV)  
 \*\*\* STEL/CEIL – STEL stands for Short-Term Exposure Limit. Usually a 15 – minute time-weighted average (TWA) exposure that should not be exceeded at any time during a workday, even if the 8-hour TWA has not been exceeded. CEIL stands for Ceiling (C) - the concentration that shall not be exceeded during any part of the working exposure.  
 NIC – TLV Notice of Intended Changes  
 NIC – WD: Notice of Intended Change; Withdraw TLV  
 SEN – TLV-confirmed potential for worker sensitization as a result of dermal contact and/or inhalation exposure, based on the weight of scientific evidence.  
 I – Measured as inhalable fraction of the aerosol  
 IV – Measured as inhalable fraction and vapor

<sub>1</sub> - Present as a natural occurring contaminant, ACGIH Threshold limit values lists Silica-Crystalline Quartz as “A2- Suspected Human Carcinogen”  
<sub>2</sub> - <1% crystalline silica (Quartz).  
 (e) - The value is for particulate matter containing no asbestos and <1% crystalline silica.  
 R – Measured as respirable fraction of the aerosol.

**OTHER INGREDIENTS / IDENTITY**

Hazardous Component(s) Chemical & Common name:	OSHA PEL	% - Optional	CAS Number
None			

**SECTION 3 – PHYSICAL & CHEMICAL CHARACTERISTICS**

Boiling Point	N/A	Solubility in Water	Less than 3%
Specific Gravity (H <sub>2</sub> O = 1)	N/A	Reactivity in Water	N/A
Vapor Pressure (mm Hg)	N/A	pH	7 – 9
Vapor Density (Air = 1)	N/A	Melting Point	N/A
Appearance and Odor	White powder with no odor		

**SECTION 4 – FIRE & EXPLOSION DATA**

Flash Point	N/A	Non-Combustible (?)	Yes
Auto-Ignition Temperature	N/A	Flammability Limits in Air (% volume)	N/A
Special Fire Fighting Procedures	None	LEL Lower	N/A
Unusual Fire and Explosion Hazards	None	UEL Upper	N/A

**SECTION 5 – PHYSICAL HAZARDS (REACTIVITY DATA)**

Stability	Unstable [ ]	Stable [ X ]
Conditions to Avoid	None	
Incompatibility (Materials to Avoid)	Acids	
Hazardous Decomposition Products	<ul style="list-style-type: none"> <li>• May release CO<sub>x</sub> when heated to decomposition</li> <li>• May release SO<sub>y</sub> when heated to decomposition</li> </ul>	
Hazardous Polymerization	Will Not Occur [ X ]	May Occur [ ]

341 West Meats Avenue, Orange, California 92865  
 Phone: (714) 974-6837 Toll Free: (866) 974-6837 FAX: (714) 637-9033

<b>SECTION 6 – HEALTH HAZARDS</b>						
Acute	Inhalation of dust may cause irritation of upper respiratory system			Chronic	Long term exposure to high dust levels may impair lung function	
Signs and symptoms of Exposure				N/A		
Medical Condition Generally Aggravated by Exposure				Respiratory problems		
Chemical Listed as Carcinogen or Potential Carcinogen	Crystalline Silica	ACGIH TLV P - [A2]	NIOSH Yes [Ca]	NTP Yes [K]	IRAC Monograph Yes – [1]	OSHA Not specified
Y – Yes N – No or Not established P-Potential						
Emergency and First Aid Procedures		Persons exposed to large amounts of airborne dust should leave the area to avoid the nuisance particulate material				
Routes of Entry		Inhalation	Remove to fresh air			
		Eyes	Wash with water for 15 minutes – call physician			
		Skin	Wash with soap and water			
		Ingestion	Call physician			

<b>SECTION 7 – SPECIAL PRECAUTIONS AND SPILL / LEAK PROCEDURES</b>	
Precautions to be taken in Handling and Storage	None
Other Precautions	None
Steps to be Taken in Case Material is Released or Spilled	Contain and Scoop materials into waste container for disposal
Waste Disposal Methods	Dispose of in accordance with all federal, state, and local regulations

<b>SECTION 8- SPECIAL PROTECTION INFORMATION/CONTROL MEASURES</b>			
Respiratory Protection (specify type)	NIOSH / OSHA approved respirator for dust when dry sanding. There is limited evidence that crystalline silica (quartz) causes cancer in humans.		
Ventilation	Local exhaust preferred; Mechanical Exhaust satisfactory	Special N/A	Other N/A
Protective Gloves	Yes		
Eye Protection	Safety glasses or goggles		
Other Protective Clothing or Equipment	None		
Work / Hygienic Practices	Avoid dry sanding. Wet sanding or sponging is preferred.		

341 West Meats Avenue, Orange, California 92865  
 Phone: (714) 974-6837 Toll Free: (866) 974-6837 FAX: (714) 637-9033


NFPA Ratings

Health: 0  
Fire: 0  
Reactivity: 0



HIMS Rating

Health: 0\*  
Fire: 0  
Reactivity: 0



0 = Minimal Hazard    1 = Slight Hazard    2 = Moderate Hazard    3 = Serious Hazard    4 = Severe Hazard

The information and data herein are believed to be accurate and have been compiled from sources believed to be reliable. It is offered for your consideration, investigation and verification. Buyer assumes all risk of use, storage and handling of the product in compliance with applicable federal, state and local laws and regulations. WestPac Materials, LLC., MAKES NO WARRANTY OF ANY KIND, EXPRESSED OR IMPLIED, CONCERNING THE ACCURACY OR COMPLETENESS OF THE INFORMATION AND DATA HEREIN. WestPac Materials, LLC., will not be liable for claims relating to any party's use of or reliance on information and data contained herein regardless of whether it is claimed that the information and data are inaccurate, incomplete or otherwise misleading.

341 West Meats Avenue, Orange, California 92865  
Phone: (714) 974-6837    Toll Free: (866) 974-6837    FAX: (714) 637-9033